

Remediation Plan for Private I/I Sources Identified in the Ottawa Road CSO Service Area

Town of Cape Elizabeth, Maine

*Presented at Town Council Workshop Session
June 15, 2015*

Presented by:


Chris Dwinal, PE

Presentation Overview

- ✓ Project History Recap
- ✓ Results of Home Inspections
- ✓ Types of Solutions
 - ✓ Example Solution
 - ✓ Proposed SD Extensions
- ✓ Proposed Plan
- ✓ Next Steps



Project History Recap



Project History Recap



CSO Permit Requirements

- ✓ 2014 – Study/Develop Phase 1 Project
- ✓ 2015 – Construct Phase 1 Project
- ✓ 2016 – Design Phase 2 Project
- ✓ 2017 – Construct Phase 2 Project
- ✓ 2018 – Construct Ottawa Rd. Pump Station Upgrade (PWD)
- ✓ 2019 – Submit CSO Master Plan update
- ✓ Focus on 2014 findings and 2015 project



Home Inspection Statistics

- Total Attempted: 188
- Total Inspected: 146
- Illicit Connections: 40

Success Rate: 78%

Types of Illicit Connections

- 20 Sump Pumps
- 22 Floor Drains
- 3 Yard Drains
- 5 Roof Leaders

Types of Solutions



Elimination of inactive sources

Redirect to a existing storm drain

Redirect on private property


Redirect to new storm drain

Proposed Solution – 1 Birchwood Road

Illicit connection:	Sump Pump Floor Drain
Possible Solutions:	Sump Pump <ol style="list-style-type: none">1. Redirect sump pump to yard2. Redirect sump pump to existing catch basin3. Do nothing Floor Drain <ol style="list-style-type: none">1. Dye test and plug if necessary2. Dye test and replace floor drain structure with sump and install second sump pump if necessary3. Do nothing
Recommended Solution:	Sump Pump: Redirect sump pump to existing catch basin Floor Drain: Dye test and replace floor drain structure with sump and install second sump pump if connected
Reasoning:	Discharge location of the floor drain is not known so dye testing is required. There is a catch basin located in front of the property for discharge of the sump pump. The floor drain becomes active when the existing sump pump is overwhelmed. If the floor drain is connected, installing a second sump pump should prevent flooding.
Interior Work Detail:	Details 1, 2, 3



Total Cost Estimate: \$180,000
Average: \$4,500
Range: \$150-\$22,000



Proposed Plan

- **Individual Solutions**
 - Work to be completed by property owner
 - Careful consideration of possible financial incentives
 - Post inspection and follow up critical
- **Town's responsibility**
 - In some cases, provide infrastructure to capture storm water from private lots
 - Look to combine with sewer replacement and/or road reconstruction work

Next Steps

A scenic landscape featuring a two-lane asphalt road with double yellow lines receding into the distance. The road is flanked by a steep, forested hillside on the left and a concrete guardrail on the right. In the background, majestic mountains with patches of snow are visible under a soft, hazy sky. The sun is low on the horizon to the right, creating a warm, golden glow and a lens flare effect. The overall mood is peaceful and forward-looking.